

ADDENDUM
June 22, 1982

Please make the following corrections to your manuals:

SWAPPING DISKETTES

Operator's Read Me First Manual
page 30.

The Model 16 Disk Operating System Owner's Manual
Section II, page 21.

Model II Owner's Manual Supplement
Section Four, Part II, page 48.

When you swap a single-sided diskette to a double-sided diskette (or double-sided to single-sided) in Drive 0, it is necessary to press the RESET switch after swapping the diskettes.

SPOOLER and DO Files

The Model 16 Disk Operating System Owner's Manual
Section II, page 40 and 80; Section III, page 180

You may not execute the SPOOL command and a DO file at the same time. The first one executed will be given priority over the second.

HELP

The Model 16 Disk Operating System Owner's Manual
Section II, page 58.

The HELP command displays only the TRSDOS-II commands and syntaxes. This will be corrected in a future release of TRSDOS-16.

KBCHAR SVC
(function code 4)

The Model 16 Disk Operating System Owner's Manual
Section III, page 164.

The Exit Conditions have been changed to:

Byte-Offset	2-3	<u>error code</u>
	6-7	<u>character present flag</u>
	8-9	<u>returned character</u>

CONFIG16/SYS

The Model 16 Disk Operating System Owner's Manual
Section III, page 164.

Assembler-16 Programming Package
Appendix D, page 336.

The CONFIG16/SYS file on your TRSDOS-16 diskette does not include the RUNCOBOL file as stated.

Thank You!

Radio Shack
A Division of Tandy Corporation
8759155